
Section of the Chassis Workshop (Revel Gear Wheel Row)

of the Kirovski Plant

2



Legend:

not to scorle Diesel engine workshop Assembly Bevel gear wheel row 19 213 (the figure probably refers 50X1-HUM to the draft number) Six Russian lathes for rough-turning lathes for fine-turning Three Russian milling machines, rough-milling of the gear wheels đ jointing planes Ten 50X1-HUM Four hussian milling machines for precision work Drilling machines for oil-holes Recently set up Russian centering machines

i Roller conveyor belt

k Two Russian bearing grinding machines

Shift norm 50 gear wheels. The maximum output is probably about 70 pieces Twenty-five bevel gear wheels of this amount are required for production while the rest goes on stock or is shipped away as spare parts. The waste percentage is about 20 percent.

CONFIDENTIAL